# Bench Scale Installation Guide




Lift tray, and remove the four yellow rubber frame protectors tags




1

Carefully, without tugging, run the cable through the column and assemble column to base




2

Assemble T-Adapter and U-bracket as shown below




3

Install indicator to U bracket with 2 knobs and connect the cable to the indicator interface port




4

Place the tray on the scale frame; Use level bubble to level the scale by adjusting the feet




5